CITY GOVERNMENT OF ZAMBOANGA

Bids and Awards Committee Villalobos St., Zamboanga City Purchase Request No.: 100-22-02-0163/February 10, 2022 CITY ASSESSOR Office of the:

Amount: **P68,900.00**

SF-GOOD-60

REQUEST FOR QUOTATION

(53.9 "Small Value Procurement")

RJM Refrigeration and Aircon Service Zamboanga Hermosa Service Specialist **AC's Service Specialist**

Date: March 22, 2022 Ouotation No.: 0079R

Place of Delivery: City General Services Office

Please quote your lowest price on the items listed below, subject to the General Conditions on the Philippine Bidding Documents on Goods, stating the shortest time of delivery and submit your quotation duly signed by your representative on or before March 30, 2022 at 10:00 a.m.

ERWIN E. BERNARDO

BAC-Chairperson

Note: ALL ENTRIES MUST BE TYPEWRITTEN / LEGIBLY WRITTEN.

- 1. DELIVERY PERIOD FIVE (5) DAYS
- 2. WARRANTY SHALL BE FOR A PERIOD OF THREE (3) MONTHS FOR EXPENDABLE SUPPLIES, ONE (1) YEAR FOR NON-EXPENDABLE SUPPLIES, FROM DATE OF ACCEPTANCE BY THE PROCURING ENTITY.
- 3 PRICE VALIDITY SHALL BE FOR A PERIOD OF THIRTY (30) CALENDAR DAYS.
- G-EPS REGISTRATION CERTIFICATE SHALL BE ATTACHED UPON SUBMISSION OF THE QUOTATION, IF AVAILABLE. 4.
- BIDDERS SHALL SUBMIT ORIGINAL BROCHURES SHOWING CERTIFICATIONS OF THE PRODUCT BEING OFFERED. 5.
- INDICATE BRAND NAME OF ITEMS BEING OFFERED. 6.
- DROP YOUR QUOTATION IN A SEALED ENVELOPE AND PROPERLY LABELED-7.
- 8. Bidders are requested to submit PHILGEPS REGISTRATION NUMBER/ PHILGEPS PLATINUM CERTIFICATE. OMNIBUS SWORN STATEMENT AND BUSINESS/MAYOR'S PERMIT
- 9. Downloaded Form must be duly signed by BAC Chairman prior to submission for the opening of bidding documents. 10. For Tires and Batteries. ONE (1) YEAR WARRANTY

11. Bidders are required to indicate unit price per item, type written or legibly hand-written.

Job Order and Labor Materials 2 units 1. Koppel 3TR Floor Mounted Property No. 21140 and 20532 *Lubrication of fan motor *Servicing of mag. Contrator *General cleaning Estimated Cost: P14,400.00 2 units 2. Carrier 3TR Floor Mounted Property No. 13957 *Overhauling of condenser coil tube *Rewinding of in-door fan motor *Repair running capacitor *General cleaning Estimated Cost: P16,100.00 1 unit 3. Koppel 3TR Floor Mounted Property No. 22135 *Running Capacitor *Servicing of contactor *Servicing of contactor *Servicing of contactor *Servicing of contactor 1 unit 4. Koppel Split Type Processing system Nitrogen Estimated Cost: P16,200.00 1 unit 4. Koppel Split Type Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 1 unit 5. Split Type A/C Floor Mounted Property No. 12754-3 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 1 unit	м	ITEM & DESCRIPTION	BRAND NAME	QTY	Unit	UNIT PRICE	TOTAL
Roperty No. 21140 and 20532Image: Section of fan motor*Lubrication of fan motor*Servicing of mag. Contrator*Servicing of mag. Contrator*General cleaningEstimated Cost: P14,400.0012.Carrier 3TR Floor MountedProperty No. 139571*Overhauling of condenser coil tube*Rewinding of in-door fan motor*Repair running capacitor	J	Job Order and Labor Materials					
*Lubrication of fan motor *Servicing of mag. Contrator *General cleaning Estimated Cost: P14,400.00 2. Carrier 3TR Floor Mounted Property No. 13957 *Overhauling of condenser coil tube *Rewinding of in-door fan motor *Repair running capacitor *Repair running capacitor *Repair running capacitor *Repair running capacitor *Repair of fan motor *Repair of fan motor *Repair of mag. Contrator *Repair running capacitor *Repair of mounted Property No. 22135 *Running Capacitor *Lubrication of fan motor *Servicing of contactor *Servicing of contactor *Flushing system Nitrogen Estimated Cost: P10,200.00 4. Koppel Split Type Property No. 12754-3 *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 5. Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *W	·K	Koppel 3TR Floor Mounted		2	units		
*Servicing of mag. Contrator *General cleaning Estimated Cost: P14,400.00 I II III 2. Carrier 3TR Floor Mounted Property No. 13957 *Overhauling of condenser coil tube *Rewinding of in-door fan motor *Repair running capacitor *General cleaning Estimated Cost: P16,100.00 I unit 3. Koppel 3TR Floor Mounted Property No. 22135 *Running capacitor *Servicing of contactor *Servicing of contactor <td>Р</td> <td>Property No. 21140 and 20532</td> <td></td> <td></td> <td></td> <td></td> <td></td>	Р	Property No. 21140 and 20532					
*General Cleaning I I Estimated Cost: P14,400.00 1 unit Property No. 13957 1 unit *Overhauling of condenser coil tube *Rewinding of in-door fan motor *Rewinding of in-door fan motor *Repair running capacitor *General cleaning I III Estimated Cost: P16,100.00 I III IIII *Roppel 3TR Floor Mounted 1 IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	*]	*Lubrication of fan motor					
Estimated Cost: P14,400.00III2.Carrier 3TR Floor Mounted Property No. 13957 *Overhauling of condenser coil tube *Rewinding of in-door fan motor 	*	*Servicing of mag. Contrator					
2. Carrier 3TR Floor Mounted Property No. 13957 1 unit Property No. 13957 *Overhauling of condenser coil tube *Rewinding of in-door fan motor *Rewinding of in-door fan motor *Repair running capacitor *General cleaning Estimated Cost: P16,100.00 1 unit 3. Koppel 3TR Floor Mounted Property No. 22135 1 unit *Running Capacitor *Lubrication of fan motor *Servicing of contactor *Flushing system Nitrogen 1 unit Estimated Cost: P10,200.00 1 unit 4. Koppel Split Type Property No. 12754-3 1 unit *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas 1 unit Estimated Cost: P16,500.00 1 unit 1 unit Froeperty No. 12754-2 1 unit 1 unit *Recharging Freon gas 1 unit 1 unit *Recharging Freon gas 1 unit 1 unit *Ropel Split Type A/C Floor Mounted 1 unit 1 unit *Ropel green gas Estimate							
Property No. 13957 *Overhauling of condenser coil tube *Rewinding of in-door fan motor *Rewinding of in-door fan motor *Repair running capacitor *General cleaning Estimated Cost: P16,100.00I3.Koppel 3TR Floor Mounted Property No. 22135 *Running Capacitor *Lubrication of fan motor 							
*Overhauling of condenser coil tube *Rewinding of in-door fan motor *Repair running capacitor *General cleaning Estimated Cost: P16,100.00II3.Koppel 3TR Floor Mounted Property No. 22135 *Running Capacitor *Lubrication of fan motor *Servicing of contactor *Flushing system Nitrogen Estimated Cost: P10,200.001unit4.Koppel Split Type Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.001unit5.Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.001unit				1	unit		
*Rewinding of in-door fan motor *Repair running capacitor *General cleaning Estimated Cost: P16,100.00II3.Koppel 3TR Floor Mounted Property No. 22135 *Running Capacitor *Lubrication of fan motor *Servicing of contactor *Servicing of contactor *Flushing system Nitrogen Estimated Cost: P10,200.001unit4.Koppel Split Type Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.001unit5.Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.001unit							
*Repair running capacitor *General cleaning Estimated Cost: P16,100.00 1 3. Koppel 3TR Floor Mounted Property No. 22135 1 *Running Capacitor 1 *Lubrication of fan motor *Servicing of contactor *Flushing system Nitrogen Estimated Cost: P10,200.00 4. Koppel Split Type Property No. 12754-3 *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 5. Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00	*	*Overhauling of condenser coil tube					
*General cleaning Estimated Cost: P16,100.00 3. Koppel 3TR Floor Mounted Property No. 22135 1 *Running Capacitor *Lubrication of fan motor *Servicing of contactor *Flushing system Nitrogen Estimated Cost: P10,200.00 4. Koppel Split Type Property No. 12754-3 *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 5. Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P16,500.00	*]	*Rewinding of in-door fan motor					
Estimated Cost: P16,100.00II3.Koppel 3TR Floor Mounted Property No. 22135 *Running Capacitor *Lubrication of fan motor *Servicing of contactor *Servicing of contactor *Flushing system Nitrogen Estimated Cost: P10,200.00IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII							
3. Koppel 3TR Floor Mounted 1 unit Property No. 22135 *Running Capacitor 1 unit *Running Capacitor *Lubrication of fan motor *Servicing of contactor *Servicing of contactor *Servicing of contactor *Servicing of contactor *Illinia Illinia Illinia *Servicing of contactor *Servicing of contactor *Servicing of contactor Illinia Illinia *Servicing of contactor *Flushing system Nitrogen 1 unit Illinia Illinia *Servicing of contactor *Flushing system Nitrogen 1 unit Illinia Illinia *A Koppel Split Type 1 unit Illinia Illinia Illinia *Processing system nitrogen, vacuum *Recharging Freon gas Illinia Illinia Illinia *Split Type A/C Floor Mounted 1 unit Illinia Illinia Illinia *Voerhauling of evaporator coil, *Welding leaking tube, processor, vacuum Illinia Illinia Illinia *Welding leaking tube, processor, vacuum *Recharging Freon gas Illinia Illinia Illinia <							
Property No. 22135*Running Capacitor*Lubrication of fan motor*Servicing of contactor*Servicing of contactor*Flushing system NitrogenEstimated Cost: P10,200.004.Koppel Split TypeProperty No. 12754-3*Repair of evaporator leaking tube*Processing system nitrogen, vacuum*Recharging Freon gasEstimated Cost: P16,500.005.Split Type A/C Floor MountedProperty No. 12754-2*Overhauling of evaporator coil,*Welding leaking tube, processor, vacuum*Recharging Freon gasEstimated Cost: P11,700.00							
*Running Capacitor*Lubrication of fan motor*Servicing of contactor*Servicing of contactor*Flushing system NitrogenEstimated Cost: P10,200.004.Koppel Split TypeProperty No. 12754-3*Repair of evaporator leaking tube*Processing system nitrogen, vacuum*Recharging Freon gasEstimated Cost: P16,500.005.Split Type A/C Floor MountedProperty No. 12754-2*Overhauling of evaporator coil,*Welding leaking tube, processor, vacuum*Recharging Freon gasEstimated Cost: P11,700.00				1	unit		
*Lubrication of fan motor*Servicing of contactor*Flushing system NitrogenEstimated Cost: P10,200.004.Koppel Split TypeProperty No. 12754-3*Repair of evaporator leaking tube*Processing system nitrogen, vacuum*Recharging Freon gasEstimated Cost: P16,500.005.Split Type A/C Floor MountedProperty No. 12754-2*Overhauling of evaporator coil,*Welding leaking tube, processor, vacuum*Recharging Freon gasEstimated Cost: P11,700.00							
*Servicing of contactor *Flushing system Nitrogen Estimated Cost: P10,200.00III4.Koppel Split Type Property No. 12754-3 *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.001unitI5.Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.001unit							
*Flushing system Nitrogen Estimated Cost: P10,200.00II4.Koppel Split Type Property No. 12754-3 *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.001unit5.Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.001unit							
Estimated Cost: P10,200.00II4.Koppel Split Type Property No. 12754-3 *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.001IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII							
 4. Koppel Split Type Property No. 12754-3 *Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 5. Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00 							
Image: Second system of the							
*Repair of evaporator leaking tube *Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 5. Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00	. 13			1	unit		
*Processing system nitrogen, vacuum *Recharging Freon gas Estimated Cost: P16,500.00 5. Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00		1 0					
*Recharging Freon gas Image: Cost: P16,500.00 5. Split Type A/C Floor Mounted Property No. 12754-2 Image: Cost: P16,500.00 *Overhauling of evaporator coil, Image: Cost: P16,500.00 *Welding leaking tube, processor, vacuum Image: Cost: P16,700.00 *Recharging Freon gas Image: Cost: P11,700.00							
Estimated Cost: P16,500.0015.Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.001							
5. Split Type A/C Floor Mounted Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00							
Property No. 12754-2 *Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00							
*Overhauling of evaporator coil, *Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00				1	unit		
*Welding leaking tube, processor, vacuum *Recharging Freon gas Estimated Cost: P11,700.00							
*Recharging Freon gas Estimated Cost: P11,700.00							
Estimated Cost: P11,700.00							
	ose: Fo	or official use in the Office of the City Assessor, this ci					
Brand and Model Warranty :							

After having carefully read and accepted your General Conditions, I/We quote you on the item at prices noted above.

Printed Name / Signature

Tel. No. / Cellphone No. e-mail address

Date