

SF-GOOD-60

REQUEST FOR QUOTATION
(53.9 "Small Value Procurement")

Alex Ebol Auto Repair Shop
Zamboanga Motors Inc.
ERM Motors

Date: April 11, 2022
 Quotation No.: 0223
 Place of Delivery: City General Services Office

Please quote your lowest price on the items listed below, subject to the General Conditions on the Philippine Bidding Documents on Goods, stating the shortest time of delivery and submit your quotation duly signed by your representative **on or before April 19, 2022 at 10:00 a.m.**

ERWIN E. BERNARDO
BAC-Chairperson

Note: ALL ENTRIES MUST BE TYPEWRITTEN / LEGIBLY WRITTEN.

1. DELIVERY PERIOD **THIRTY (30) DAYS**
2. WARRANTY SHALL BE FOR A PERIOD OF THREE (3) MONTHS FOR EXPENDABLE SUPPLIES, ONE (1) YEAR FOR NON-EXPENDABLE SUPPLIES, FROM DATE OF ACCEPTANCE BY THE PROCURING ENTITY.
3. PRICE VALIDITY SHALL BE FOR A PERIOD OF THIRTY (30) CALENDAR DAYS.
4. G-EPS REGISTRATION CERTIFICATE SHALL BE ATTACHED UPON SUBMISSION OF THE QUOTATION, IF AVAILABLE.
5. BIDDERS SHALL SUBMIT ORIGINAL BROCHURES SHOWING CERTIFICATIONS OF THE PRODUCT BEING OFFERED.
6. **INDICATE BRAND NAME OF ITEMS BEING OFFERED.**
7. **DROP YOUR QUOTATION IN A SEALED ENVELOPE AND PROPERLY LABELED-**
8. **Bidders are requested to submit PHILGEPS REGISTRATION NUMBER/ PHILGEPS PLATINUM CERTIFICATE, OMNIBUS SWORN STATEMENT, LATEST ITR AND BUSINESS/MAYOR'S PERMIT**
9. **Downloaded Form must be duly signed by BAC Chairman prior to submission for the opening of bidding documents.**
10. **For Tires and Batteries, ONE (1) YEAR WARRANTY**
11. **Bidders are required to indicate unit price per item, type written or legibly hand-written.**

| ITEM NO. | ITEM & DESCRIPTION | BRAND NAME | QTY | Unit | UNIT PRICE | TOTAL |
|----------|---|------------|-----|------|------------|-------|
| | JOB ORDER FOR LABOR AND MATERIALS | | | | | |
| 1. | Ford Ranger FRD-942 Property no. 21438-1 Check up of electrical system. Repair, replace strobe light assembly, headlight, signal light, body control unit assembly and reprogram of control unit Estimated Cost: P88,400.00 | | 1 | unit | | |
| 2. | Mitsubishi L-300 SJF-315 Property no. 18735 Body repair, painting of damaged portion. Repair of underchassis suspension, replace damaged lower ball joint, swing arm, shaft, swing arm damper, center post, bell crank, idler arm, tie rod end and lift spring bushing Upholstery, replace door sliding, check up of engine, repair, replace, fuel filter, oil filter, air filter, water pan, fan belt, steering fan belt and alternator hose Check up of electrical light, repair, replace front light corner lamp and bumper lamp. Check up of aircon, repair, replace expansion valve, filter dryer, O-ring and auxillary motorfan Estimated Cost: P217,571.00 | | 1 | unit | | |
| 3. | Ford Ranger FRD-982 Property no. 21961 Repair and painting of body damage portion, replace of damaged windshield with rubber seal. Replace tail light assembly left side, replace hood damper shock L/R, change oil and replace oil filter Estimated Cost: P141,200.00 | | 1 | unit | | |
| 4. | Mitsubishi L-300 SJE-986 Property no. 20390 Check up of front suspension, repair, replace front shock absorber L/R, drag link, wheel alignment and strut bar bushing Replace damage windshield, check up brake, repair, replace caliper kit and cylinder kit Estimated Cost: P35,700.00 | | 1 | unit | | |
| 5. | Mitsubishi L-300 SJF-324 Property no. 18733 General body repair, general body painting and upholstery. Check up underchassis suspension, repair, | | 1 | unit | | |

| | | | | | | |
|---|--|--|---|------|--|--|
| | replace lower ball joint, swing arm shaft, bell cram, center poat, idler arm, tie rod end, stabilizer bushing, strut bar bushing and lift spring bushing Check up of brake system, repair, replace brake lining, cylinder repair kit, front brake pad and caliper repair kit Check up of engine, repair, replace water fan belt, steering fan belt, change oil, oil filter, fuel filter and air filter. Engine tune up and calibration of injection pump Check up of electrical light, repair, replace tail light, corner lamp and wiper blade. Repair and replace windshield glass assembly. Estimated Cost: P220,000.00 | | | | | |
| 6. | Ford Ranger C1-D160 Property no. 22551 Body repair and body painting, repair and replace damaged windshield glass with sealer. Repair and replaced damaged tail light assembly L/R. Check up of low power engine, repair and replace turbo inter cooler, tank pump, pressure valve reprogram and testing. Estimated Cost: P181,440.00 | | 1 | unit | | |
| Purpose: for official use in the Office of the City Mayor-Peace and Order , this city | | | | | | |

Brand and Model _____
Delivery Period : _____
Warranty : _____
Price Validity : _____

After having carefully read and accepted your General Conditions, I/We quote you on the item at prices noted above.

Printed Name / Signature

Tel. No. / Cellphone No.
e-mail address

Date