

SF-GOOD-60

**REQUEST FOR QUOTATION
(53.9 "Small Value Procurement")**

**RJN Auto Repair
Teody Auto Repair Shop
Alex Ebol Auto Repair Shop**

Date: March 06, 2023

Quotation No.: 0164

Place of Delivery: City General Services Office

Please quote your lowest price on the items listed below, subject to the General Conditions on the Philippine Bidding Documents on Goods, stating the shortest time of delivery and submit your quotation duly signed by your representative **on or before March 10, 2023 at 10:00 a.m.**

ATTY. ALEXANDER ERIC F. ELIAS
BAC-Chairperson

Note: ALL ENTRIES MUST BE TYPEWRITTEN / LEGIBLY WRITTEN.

1. DELIVERY PERIOD **TWENTY (20) CALENDAR DAYS**
2. WARRANTY SHALL BE FOR A PERIOD OF THREE (3) MONTHS FOR EXPENDABLE SUPPLIES, ONE (1) YEAR FOR NON-EXPENDABLE SUPPLIES, FROM DATE OF ACCEPTANCE BY THE PROCURING ENTITY.
3. PRICE VALIDITY SHALL BE FOR A PERIOD OF THIRTY (30) CALENDAR DAYS.
4. G-EPS REGISTRATION CERTIFICATE SHALL BE ATTACHED UPON SUBMISSION OF THE QUOTATION, IF AVAILABLE.
5. BIDDERS SHALL SUBMIT ORIGINAL BROCHURES SHOWING CERTIFICATIONS OF THE PRODUCT BEING OFFERED.
6. **INDICATE BRAND NAME OF ITEMS BEING OFFERED.**
7. **DROP YOUR QUOTATION IN A SEALED ENVELOPE AND PROPERLY LABELED-**
8. **Bidders are requested to submit PHILGEPS REGISTRATION NUMBER/ PHILGEPS PLATINUM CERTIFICATE, OMNIBUS SWORN STATEMENT AND BUSINESS/MAYOR'S PERMIT**
9. **Downloaded Form must be duly signed by BAC Chairman prior to submission for the opening of bidding documents.**
10. **For Tires and Batteries, ONE (1) YEAR WARRANTY**
11. **Bidders are required to indicate unit price per item, type written or legibly hand-written.**

ITEM NO.	ITEM & DESCRIPTION	BRAND NAME	QTY	Unit	UNIT PRICE	TOTAL
	Job Order, Labor and Materials					
1.	Repair of one (1) unit Toyota Hilux, plate no. SFM-491 (PN: 12929) Scope of work: Repair of alternator, Battery Charging, check-up wiring connections, fuse and relays Estimated Cost: P7,280.00		1	Unit		
2.	Repair of one (1) unit Mitsubishi L-300 with plate no. SJF-272 (PN: 17713) Scope of work: Repair of under chassis, replacement of ball joint (L/R) upper and lower, brake pad, tie rod end (L/R), outer center post bushing, Idler post, repair of aircon, replacement, replacement of fan belt, change engine oil, oil filter, transmission oil, brake fluid, repair steering pump, add ATF Estimated Cost: P123,488.00		1	Unit		
3.	Repair of one (1) UNIT Motor, Honda XRM 10901 (PN: 18762) Scope of Work: Replace drive chain and sprocket (F/R), change oil and engine check tune up, seat upholstery, check up wiring connection, replace tire rim, replace brake shoe/brake pad and starter Estimated Cost: P17,375.00		1	Unit		
4.	Repair of one (1) unit Toyota Tamaraw FX with plate no. SEM-543 (PN: 11757) Scope of Work: Change engine oil and oil filter, repair brake system (F/R), change wheel bearing (R), change stabilizer bar link, replace piston caliper brake pad, brake shoe, brake rubber cap and welding muffler. Estimated Cost: P82,380.00		1	Unit		

Purpose: For official use of City Health Office, this city

Brand and Model : _____
Delivery Period : _____

Warranty : _____
Price Validity : _____

After having carefully read and accepted your General Conditions, I/We quote you on the item at prices noted above.

Printed Name / Signature

*Tel. No. / Cellphone No.
e-mail address*

Date