

SF-GOOD-60

**REQUEST FOR QUOTATION
(53.9 "Small Value Procurement")**

**Teody Auto Repair Shop
RJN Auto Repair
Zamboanga Motors, Inc.**

Date: April 12, 2022
Quotation No.: 0252
Place of Delivery: City General Services Office

Please quote your lowest price on the items listed below, subject to the General Conditions on the Philippine Bidding Documents on Goods, stating the shortest time of delivery and submit your quotation duly signed by your representative **on or before April 22, 2022 at 10:00 a.m.**

ERWIN E. BERNARDO
BAC-Chairperson

Note: ALL ENTRIES MUST BE TYPEWRITTEN / LEGIBLY WRITTEN.

1. DELIVERY PERIOD **SIXTY (60) DAYS**
2. WARRANTY SHALL BE FOR A PERIOD OF THREE (3) MONTHS FOR EXPENDABLE SUPPLIES, ONE (1) YEAR FOR NON-EXPENDABLE SUPPLIES, FROM DATE OF ACCEPTANCE BY THE PROCURING ENTITY.
3. PRICE VALIDITY SHALL BE FOR A PERIOD OF THIRTY (30) CALENDAR DAYS.
4. G-EPS REGISTRATION CERTIFICATE SHALL BE ATTACHED UPON SUBMISSION OF THE QUOTATION, IF AVAILABLE.
5. BIDDERS SHALL SUBMIT ORIGINAL BROCHURES SHOWING CERTIFICATIONS OF THE PRODUCT BEING OFFERED.
6. **INDICATE BRAND NAME OF ITEMS BEING OFFERED.**
7. **DROP YOUR QUOTATION IN A SEALED ENVELOPE AND PROPERLY LABELED-**
8. **Bidders are requested to submit PHILGEPS REGISTRATION NUMBER/ PHILGEPS PLATINUM CERTIFICATE, OMNIBUS SWORN STATEMENT, LATEST ITR AND BUSINESS/MAYOR'S PERMIT**
9. **Downloaded Form must be duly signed by BAC Chairman prior to submission for the opening of bidding documents.**
10. **For Tires and Batteries, ONE (1) YEAR WARRANTY**
11. **Bidders are required to indicate unit price per item, type written or legibly hand-written.**

ITEM NO.	ITEM & DESCRIPTION	BRAND NAME	QTY	Unit	UNIT PRICE	TOTAL
	JOB ORDER FOR LABOR AND MATERIALS					
1.	MITSUBISHI L300 SJE-983 Property no. 19284 General under chassis repair, check up engine hard starting and tune up engine, change oil filter and change oil. Break system repair. Pullout injection pump and calibrate and balancing. Pullout injector calibrate and balancing. Change brake pad L/R, brake shoe L/R. Change center post bushing, idler post bushing. Change ball joint lower and upper L/R. Change tie rod end inner and outer L/R. Change fuel filter. Heater glow plug. Change injection pump nozzle tip, injector nozzle tip. 1 set brake pad L/R, 1 set brake shoe L/R, 2 pcs ball joint lower L/R, 2pcs ball joint upper L/R, 2pcs center post bushing, 2 pcs idler post bushing, 2pcs tie rod end outer, 2pcs tie rod end inner, 1pc oil filter, 1pc fuel filter, 4pcs heater glow plug, 4pcs injector nozzle tip, 4pcs injection pump nozzle tip and 1liter brake fluid. Estimated Cost: P136,500.00		1	Unit		
2.	MITSUBISHI STRADA SEM-220 Property no. 12039 Pullout injection pump calibrate and balancing, pullout injector calibrate and balancing. Tune up engine, repair turbo, repair engine leak. Change valve cover gasket, change injection pump nozzle tip, change injector nozzle tip and change alternator pressure host. 4 pcs injection pump nozzle tip, 4 pcs injector tip and 4pcs alternator pressure host. Estimated Cost: P78,700.00		1	Unit		
3.	TOYOTA HILUX SAA-7201 Property no. 20903 Change wiper blade, change hood shock absorber, change signal light valve, check up backing sensor, adjust brake rear wheel L/R and adjust hand break. 2pcs wiper blade, 2pcs hood shock absorber and 2pcs signal light valve L/R rear Estimated Cost: P64,700.00		1	Unit		
4.	MITSUBISHI L-300 SEM-251 Property no. 12521 Body repair damage portion, body painting (wash over),		1	Unit		

	<p>under chassis repair, repair electrical wiring, engine repair, pullout transmission, brake system repair and under chassis coating. Change ball joint lower and upper L/R, change center post bushing, idler post bushing, change tie rod end inner and outer L/R, change brake pad L/R, brake shoe L/R, change stoplight, signal light L/R and change clutch pressure, clutch disc, release bearing.</p> <p>1 set brake pad L/R, 1 set brake shoe L/R, 2 pcs ball joint lower L/R, 2pcs ball joint upper L/R, 2pcs center post bushing, 2pcs idler post bushing, 1 clutch pressure, 1 clutch disc, 1 pc release bearing, 2pcs tie rod end inner and outer L/R, 2pcs stoplight L/R, 2pcs signal light L/R, 1 liter brake fluid</p> <p>Estimated Cost: P36,000.00</p>					
5.	<p>5. MITSUBISHI STRADA SGD-535 Property no, 15390 Under chassis repair, pullout rear spring right, pullout rear spring left, replace secondary and third leaf spring L/R, aircon repair. Change oil, change oil filter and replace wheel alignment. Change secondary clutch repair kit, change aircon blower and replacement and change clutch master.</p> <p>1 pc oil filter, 1pcs aircon blower, 2pcs secondary leaf spring, 1set secondary clutch repair kit, 8pcs rear spring bushing, L/R, 2pcs center volt, 1pc clutch master and 1 liter fluid</p> <p>Estimated Cost: P270,200.00</p>		1	Unit		
Purpose: For official use in the Office of the City Mayor, this city						

Brand and Model : _____
Delivery Period : _____
Warranty : _____
Price Validity : _____

After having carefully read and accepted your General Conditions, I/We quote you on the item at prices noted above.

Printed Name / Signature

Tel. No. / Cellphone No.
e-mail address

Date